## LASER®

## **Battery Tester**

Easy to read with floating discs showing level of charge. Temperature compensating allows hot or cold temperature testing. Readings in both specific gravity and percentage charge. Range 1.145 to 1.260sg CAUTION: Battery acid causes severe burns. Wear protective clothing and goggles when handling batteries. NB. Rinse tester with water after use.



## **Additional Information**

- · Battery tester for lead acid batteries.
- · Easy to read with floating discs showing level of charge.
- · Temperature compensation allows for hot or cold temperature testing.
- · Readings in both specific gravity and percentage charge.
- Range: 1.145 1.260sg.

http://lasertools.co.uk/product/4294





429







18 Oct 2024