LASER®

Broken Glow Plug Tip Puller Kit M8 w/o cleaning tools

Broken Glow Plug Tip removal kit for M8 glow plugs supplied without cleaning tools. If cleaning tools required, please see Laser Part No. 6646.



Additional Information

- Applications include: M8 x 1mm glow plug tip extraction tools.
- Unique extended drill bits with crimped and welded ends for increased access and a built in depth control collar to ensure the maximum • depth cannot be exceeded.
- Specially machined thread taps, crimped and welded to extra-long extensions for increased access.
- Due to the size of individual threaded components and the nature of the task, all components should be considered consumable. Spare • parts are available.
- Always follow instructions provided. NOTE: For PSA M8 see 7739.

http://lasertools.co.uk/product/7733







18 Oct 2024